

### Vehicle Inspection Report

**Make** Honda  
**Model** Nc 750 Sa-h - 745cc  
**Date Inspected:** 10/06/2025 16:24  
**Signed By** MAG Inspections

### Vehicle

**Reg** LB67WZO  
**Agree No**  
**VIN** JH2RC88A2HK101834

### Grade

**Bronze**

### Motorbike Details

<b>Engine Size</b>		<b>Mileage</b>	21,279 miles	<b>Gears</b>	
<b>Colour</b>	Red	<b>Fuel</b>	Petrol	<b>Fuel Level</b>	
<b>Trans</b>	Manual	<b>DFR</b>		<b>YOM</b>	
<b>Non-run</b>	No	<b>Ser Dam</b>	No	<b>Police</b>	No
<b>MOT Location</b>		<b>MOT Expiry</b>	23/03/2026		

### Miscellaneous

<b>V5 Location</b>	
<b>No. of Former Keepers</b>	3
<b>No. Keys</b>	
<b>Spare Key</b>	No
<b>Service History</b>	No

### Tyres & Wheels

**Front Tyre** 3mm-5mm Pirellii  
**Rear Tyre** 3mm-5mm Pirellii

### Interior Condition

**Trim Condition** Average  
**Seats** Average

### Extras

<b>Metallic Paint</b>	No
<b>Cruise Control</b>	
<b>Phone Kit</b>	No

### Beauty Shots





Photos



Damage Assessment



**Roof**  
 Scratched  
 Over 25mm  
 Thru Paint  
 Refinish



**Qtr Panel osr**  
 Chipped  
 1 To 5  
 Smart Repair



**Qtr Panel Arch Extension os**  
 Scratched (Painted)  
 Over 25mm  
 Thru Paint  
 Smart Repair



**Bumper Front**  
 Chipped  
 Multiple Chips  
 Smart Repair



**Door Mirror Assy nsf**  
 Scuffed (Unpainted)  
 Over 100mm  
 Smart Repair



**Sill ns**  
 Chipped  
 Over 5mm  
 Refinish



**Handle Inner nsf**  
 Damaged  
 Needs Replaced  
 Replace

## Damage Lines

<b>Component</b>	<b>Condition</b>	<b>Severity</b>	<b>Repair</b>
Roof	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Qtr Panel Arch Extension os	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Bumper Front	Chipped	Multiple Chips	Smart Repair
Door Mirror Assy nsf	Scuffed (Unpainted)	Over 100mm	Smart Repair
Sill ns	Chipped	Over 5mm	Refinish
Handle Inner nsf	Damaged	Replace	Replace

## Comments