



Vehicle Inspection Report

Make Honda

Model Nss 125 Ad-k - 125cc

Date Inspected: 17/06/2025 10:12

Signed By MAG Inspections

Vehicle

Reg YX68LVG

Agree No

VIN ZDCJF69A0KF050404

Grade

Bronze

Motorbike Details

Engine Size Mileage
Colour Grey Fuel
Trans DFR

Non-runNoSer DamMOT LocationMOT Expiry

16,206 miles Gears

Petrol Fuel Level

YOM

No **Police** No

27/04/2026

Miscellaneous

V5 Location

No of Former Keepers 1

No. Keys

Spare Key No Service History No

Tyres & Wheels

Front Tyre 3mm-5mm Other
Rear Tyre 3mm-5mm Other

Interior Condition

Trim Condition Average
Seats Poor

Extras

Metallic Paint No

Cruise Control

Phone Kit No

Beauty Shots



















Photos







Damage Assessment



Seat Back Cover osf Holed Over 3mm Replace



Qtr Panel osr Scratched Over 25mm Thru Paint Refinish



Arch Extension os Scuffed (Unpainted) Over 100mm Smart Repair


Qtr Panel



Sill os Scratched Over 25mm Thru Paint Refinish



Door osf Scratched Over 25mm Thru Paint Refinish



Wing osf Cracked Needs Replaced Replace



Door Mirror Assy osf Scuffed (Unpainted) Over 100mm Smart Repair



Bonnet
Cracked
Needs
Replaced
Replace



Bumper Front Scratched 25 to 100mm Thru Paint Smart Repair



Door Mirror Assy nsf Broken Needs Replaced Replace



Wing nsf
Scratched
Over 25mm
Thru Paint
Refinish



Sill ns
Cracked
Needs
Replaced
Replace



Qtr Panel nsr Scratched Over 25mm Thru Paint Refinish

Damage Lines Component Condition Severity Repair Seat Back Cover osf Holed Over 3mm Replace Qtr Panel osr Scratched Over 25mm Thru Paint Refinish Qtr Panel Arch Extension os Scuffed (Unpainted) Over 100mm Smart Repair Sill os Scratched Over 25mm Thru Paint Refinish Door osf Scratched Over 25mm Thru Paint Refinish Wing osf Cracked Replace Replace Door Mirror Assy osf Scuffed (Unpainted) Over 100mm Smart Repair Bonnet Cracked Replace Replace **Bumper Front** Scratched 25 to 100mm Thru Paint Smart Repair Door Mirror Assy nsf Broken Replace Replace Over 25mm Thru Paint Scratched Refinish Wing nsf Sill ns Cracked Replace Replace Qtr Panel nsr Scratched Over 25mm Thru Paint Refinish

Co	mr	ne	ni	S
\sim		110		