

Vehicle Inspection Report

Date Inspected: 13/05/2025 16:40
Inspected By: Levi Ogden

Reg: SD17WYJ

VIN: VF3CCHMZ6HW019273

Valuation

Cap ID	69414
Cap Clean	£0
Cap Average	£0
Cap Below	£0

NAMA Grading



Grade

3

Appraised By: MAG Inspections

General Details

Make	Peugeot	Transmission	Manual
Model	208 Allure - 1200cc	Date First Reg	31/03/2017
Body Type	Hatchback	Doors	5
Fuel Type	Petrol	Colour	White
		Year of MFR	2017

Tyres & Wheels

OSF Depth	Wheel Trims
NSF Depth	Alloys
OSR Depth	Spare
NSR Depth	Tyre Comments

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Good
Odour	No
Comments	

Miscellaneous

V5 Location	
MOT Location	
MOT Expiry	03/06/2025

Equipment

Nav Pre Wired	F&R Parking Sensors	Cruise Control
	Bluetooth	Auto Headlights
		A/C
		Metallic Paint

Service History

Service None
History
Stamps



Damage Assessment



Door osf
Scratched
UpTo 25mm
Not Thru Paint
Machine Polish



Door osr
Scratched
UpTo 25mm
Not Thru Paint
Machine Polish



Qtr Panel osr
Poor Previous
Repair
Poor Paint
Refinish



Bumper Rear
Scratched
25 to 100mm
Thru Paint
Smart Repair



Qtr Panel nsr
Dented
2 Or Less
UpTo 10mm
Smart Repair



Wing nsf
Scratched
UpTo 25mm
Not Thru Paint
Machine Polish



Bonnet
Poor Previous
Repair
Poor Paint
Refinish

Comments