

Vehicle Inspection Report

Make Yamaha
Model Gpd125-a Nmax 125 Abs
- 125cc
Date 05/05/2025 15:39
Inspected:
Signed By MAG Inspections

Vehicle

Reg LF24ZYM
Agree No
VIN MH3SEG51000044675

Grade

Gold

Motorbike Details

Engine Size		Mileage	659 miles	Gears	
Colour	Red	Fuel	Petrol	Fuel Level	
Trans		DFR		YOM	
Non-run	No	Ser Dam	No	Police	No
MOT Location		MOT Expiry			

Miscellaneous

V5 Location	
No of Former Keepers	0
No. Keys	
Spare Key	No
Service History	No

Tyres & Wheels

Front Tyre 3mm-5mm Dunlop
Rear Tyre 3mm-5mm Dunlop

Interior Condition

Trim Condition Good
Seats Good

Extras

Metallic Paint No
Cruise Control
Phone Kit No

Beauty Shots






Photos




Damage Assessment



Wing osf
Scratched
UpTo 25mm
Thru Paint
Smart Repair



Qtr Panel osr
Scratched
Over 25mm
Not Thru Paint
Machine
Polish



Spoiler Rear
Scratched
(Painted)
Over 25mm
Thru Paint
Smart Repair



Qtr Panel nsr
Scratched
Over 25mm
Not Thru Paint
Machine
Polish

Damage Lines

Component	Condition	Severity	Repair
Wing osf	Scratched	UpTo 25mm Thru Paint	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Spoiler Rear	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish

Comments